

## RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080148-05

2561 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 3-13-77

P.O. NO.

VENDOR PACKING SLIP NO.

PLANT #9

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OFER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	322	0	39	C	22		93		R	
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	ACCEPTED	REJECTED	REMARKS
3	738318 Time Delay Assembly						3			

RECEIVED BY  
HMC-105

INSPECTED BY

Dura 3/13/77

REJECTS RETURNED  
ON SHIP. MEMO NO.

RECEIVED FROM

DATE REC'D. 3-13-77

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OFER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	322	0	9	0	20					
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	ACCEPTED	REJECTED	REMARKS
2	738298 Bracket Assembly Switch Adjust						2			

RECEIVED BY  
HMC-105

INSPECTED BY

Dura 3/13/77

REJECTS RETURNED  
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080148-0